


EXISTING DOCKS, BOATLIFTS AND MOORING PILING SHALL NOT BE RELOCATED FURTHER SEAWARD FROM THE EXISTING MARINE IMPROVEMENTS


- 1 FACE OF NEW SEAWALL NOT TO EXCEED 12" SEAWARD OF THE EXISTING SEAWALL FACE
- 2 MOORING PILE TO REMAIN DURING CONSTRUCTION
- 3 EXISTING CONCRETE CANTILEVER DOCK TO BE REMOVED SEAWARD FROM EXISTING SEAWALL NOT TO BE REPLACED.
- 4 EXISTING WOOD DOCK TO BE REMOVED DURING CONSTRUCTION TO BE REPAVED SAME FOOT PRINT NO FURTHER SEAWARD THAN EXISTING EXISTING PILING TO REMAIN DURING CONSTRUCTION.
- 5 EXISTING BOAT LIFT AND PILING TO REMAIN DURING CONSTRUCTION. EXISTING DECKING TO BE REMOVED AS NECESSARY TO ALLOW CONSTRUCTION OF THE NEW SEAWALL REPAIR & REPLACED. NOT TO EXCEED SEAWARD FURTHER THAN THE EXISTING MARINE ELEMENTS.

DATA SHEET
 PANEL SIZE : 10' VINYL REPAIR
 CANAL: "SALTWATER"
 1209 ISABEL DR
 SANIBEL, FL. 33951
 Strap# 18-46-23-T3-00300.022B
 SANIBEL HARBOURS Lts 22-23

rev 08/27/2024
 Added sheet 2/2
 Site Plan
 rev 08/19/20024
 rev 08/19/20024
 07/19/2024



SITE PLAN



Digitally signed
 by James
 Andrew
 Schivinski PE
 Date: 2024.08.27
 12:31:43 -04'00'

ENGINEERING & DESIGN CONSULTANTS, INC.
 P.O.Box 100521 Cape Coral, FL. 33910
 jim@engineeringdesignl.com
 239-470-0105
 Copyright 2021 CA#6178